



The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER

Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives	Present During	the Inspection:

OGM Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0410002	
Inspection Type:	PARTIAL	
Inspection Date:	Tuesday, April 13, 2010	
Start Date/Time:	4/13/2010 7:30:00 AM	
End Date/Time:	4/13/2010 2:30:00 PM	
Last Inspection:	Tuesday, March 16, 2010	

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Overcast/Snowing, Temp. 29 Deg. F.

InspectionID Report Number: 2324

Accepted by: jhelfric

5/6/2010

Permitee: CANYON FUEL COMPANY LLC

Operator: CANYON FUEL COMPANY LLC

Site: SUFCO MINE

Address: 397 S 800 W, SALINA UT 84654

County: SEVIER

Total Disturbed

Phase I

Phase II

Phase III

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

25,292.43 Total Permitted

Current Acreages

48.43

Mineral Ownership

Types of Operations

✓ Federal✓ StateCountyFeeOther

✓ Underground☐ Surface

□ Loadout□ Processing

Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Sand. Lauskupe

Date

Tuesday, April 13, 2010

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0410002 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 13, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	~		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	V			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0410002 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 13, 2010

Page 3 of 3

2. Signs and Markers

Mine identification signs are located at the points of public access to the permit area. The signs contain the required information.

4.a Hydrologic Balance: Diversions

LeLand Roberts, SUFCO, notified the Division the week prior to this inspection that an internal inspection revealed that the undisturbed bypass culvert system has a segment that has partially collapsed. The segment lays beneath the area by the coal storage pile and fuel storage area. Arrangements were made and an additional fuel storage tank with containment is on site to allow the area to be excavated and the CMP to be repaired.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile had a light coating of snow over the entire pile from the snow storm that was occurring during the inspection. The pile appeared stable.